EAST Search History

L17	10694	(foamed or foam or foamable or foaming or blowing or expandable) near2 core	US-PGPUB; USPAT	OR	ON	2006/10/19 14:40
L18	12644	(osb or (strand or wafer or chip or gypsum) adj board or strandbaord or chipboard or waferbaord or gypsumboard) same17	US-PGPUB; USPAT	OR	ON	2006/10/19 14:49
L19	12644	(osb or ((strand or wafer or chip or gypsum) adj board) or strandbaord or chipboard or waferbaord or gypsumboard) same17	US-PGPUB; USPAT -	OR	ON	2006/10/19 14:50
L20	3175	(strandbaord or chipboard or waferbaord or gypsumboard) same17	US-PGPUB; USPAT	OR	ON	2006/10/19 14:47
L21	9967	(osb or ((strand or wafer or chip or gypsum) adj board)) same17	US-PGPUB; USPAT	OR	ON	2006/10/19 14:46
L22	3176	(strandbaord or chipboard or waferbaord or gypsumboard) with17	US-PGPUB; USPAT	OR	ON	2006/10/19 14:48
L23	3387	(strandboard or chipboard or waferbaord or gypsumboard) with17	US-PGPUB; USPAT	OR	ON	2006/10/19 14:49
L24	2030	@ad<="20000101" and 23	US-PGPUB; USPAT	OR	ON	2006/10/19 14:48
L25	108	(osb or ((strand or wafer or chip or gypsum) adj board) or strandbaord or chipboard or waferbaord or gypsumboard) same 17	US-PGPUB; USPAT	OR	ON	2006/10/19 14:50
L26	71	("0919057" "1250594" "1474657" "2111922" "2875478" "3496058" "3557840" "3654053" "3692620" "3731449" "3753843" "3857217" "3911554" "4004387" "4024684" "4032689" "4037377" "4051641" "4068437" "4147004" "4169688" "4170859" "4283898" "4402170" "4430833" "4443988" "4471591" "4510019" "4514532" "4671038" "4704837" "4726973" "4765105" "4786547" "4802837" "4856244" "4865912" "4932171" "4961298" "4964933" "5058333" "5062250" "5081810" "5140086" "5194323" "5224315" "5269109" "5345738" "5428929" "5433050" "5497589" "5509242" "5519971" "5573829" "5628158" "5638651" "5641553" "5755068" "5842314" "5950389" "5953883" "6136408" "6240704"). PN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/10/19 14:53

EAST Search History

L27	· 71	("0919057"	"1250594"	"1474657"	US-PGPUB;	OR	ON	2006/10/19 14:53
		"2111922"	"2875478"	"3496058"	USPAT;			
				"3692620"	USOCR			
		"3731449"	"3753843"	"3857217"			`	
		"3911554"	"4004387"	"4024684"				
		"4032689"	"4037377"	"4051641"				
		"4068437"	"4147004"	"4169688"			İ	
		"4170859"	"4283898"	"4402170"				
		"4430833"	"4443988"	"4471591"				
		"4510019"	"4514532"	"4671038"				
		"4704837"	"4726973"	"4765105"				
		"4786547"	"4802837"	"4856244"				
		"4865912"	"4932171"	"4961298"				
		"4964933"	"5058333"	"5062250"				
		"5081810"	"5140086"	"5194323"				
		"5224315"	"5269109"	"5345738"				
		"5428929"	"5433050"	"5497589"				
		"5509242"	"5519971"	"5573829"				
		"5628158"	"5638651"	"5641553"		[
		"5755068"	"5842314"	"5950389"				
		"5953883"	"6136408"	"6240704").				
		PN.						

BEST AVAILABLE COPY

[0005] There still exists a need for a nonwoven fiber glass mat that has better flame resistance, lower cost and good

fire retardant or intumescent material, adhesives, colorants and/or other materials for changing the appearance or per-

formance of the mat surface.